



SAFETY ALERT



FATALITY

While conducting a day reconnaissance mission in mountainous terrain, an AH64 crew performed a decelerating left turn at low altitude, experienced low rotor RPM, and descended into the ground. This accident resulted in one fatality, one serious injury, and a total aircraft loss.



Important information to remember

- Always calculate, brief, and verify aircraft performance capabilities
- Crews should discuss contingencies and emergencies, such as when to jettison external stores
- Utilize good crew coordination; direct/offer assistance
- Remember the two challenge rule always requires time to react

S
A
F
E
T
Y

A
L
E
R
T

S
A
F
E
T
Y

A
L
E
R
T

S
A
F
E
T
Y

A
L
E
R
T

S
A
F
E
T
Y

A
L
E
R
T