


TF MULESKINNER MAINTENANCE SAFETY ALERT #2



TF MULESKINNER SAFETY
AFGHANISTAN 12-15



TF MULESKINNER MAINTENANCE SAFETY ALERT #2

TF MULESKINNER MAINTENANCE SAFETY ALERT #2

Damage noted is not all-inclusive


Blown Engine



Auto Lube Reservoir Empty



Auto Lube Line Disconnected
and Grease Fitting Installed on
Some, Bolts Sheared and Other
Damaged Parts



Summary

- No Wash Rack Available to Keep Equipment Clean
- Soldiers not Performing Critical Maintenance
- RT 240 V2 Has A Blown Engine
- Exact Cost to Repair Unknown
- Initial Estimate \$70K+
- Currently no Shelter in Place to Tear Down
- Tools Not on Site To Repair
- Only 268 Hours Since Reset
- Soldiers Stated "They Cannot get Oil"

Anti-freeze all inside cab. Would only run 20 minutes at a time and then Radiator Hose would blow off. The hose would be put back on and it would run until the hose blew off again; no Anti-freeze was added, this was done until it wouldn't run any more



So Much Oil in Radiator;
Almost Turned to Grease

TF MULESKINNER SAFETY CONTACT DSN (318)431-3546/3305 ROSHAN (079)985-5997

Think War – Do Right – Build Teams – Eliminate Hassle – Grow Leaders