

# GEAR UP!

## FOR WINTER OPS

Good all-around visibility is essential to safe cold weather driving. To achieve optimum visibility during cold weather:

- Remove all ice, snow and fog from all windows before operating the vehicle.
- Keep all windows and mirrors clear at all times during operations.
- Use defrosters and windshield wipers to keep the windshield free of ice, sleet, snow and fog.
- Keep inside and outside rearview mirrors clean and properly adjusted.
- Use headlights during snowstorms and periods of reduced visibility according to local SOPs and the tactical situation.
- Increase gaps between vehicles when exhaust gases cause ice fog.
- Use a ground guide when backing the vehicle or where assistance is required in picking a trail in deep snow.

SOURCE: FIELD MANUAL 55-30, ARMY MOTOR TRANSPORT UNITS AND OPERATIONS, APPENDIX G, VEHICLE OPERATIONS IN ADVERSE WEATHER

ARMY SAFE  
**FALLWINTER**  
NO TIME TO CHILL



U.S. ARMY  
ARMY STRONG™



U.S. ARMY COMBAT READINESS/SAFETY CENTER  
<https://safety.army.mil>

ARMY SAFE  
IS ARMY STRONG

A BAND OF BROTHERS  
& SISTERS

TOW/  
TIE  
DOWN

TOW/  
TIE  
DOWN

WINCH BRAKE  
T-CASE NEUTRAL