



DEPARTMENT OF DEFENSE  
HEADQUARTERS, US FORCES-AFGHANISTAN  
NEW KABUL COMPOUND, KABUL, AFGHANISTAN  
APO AE 09356



# FATALITY

## ***Service member killed in a recent Non-Tactical Vehicle rollover accident.***

On 3 August 2011, three service members were traveling down a unimproved road when the driver lost control. The vehicle left the roadway and flipped, rolling over an estimated six (6) times, coming to rest on its wheels. The driver of the vehicle died from his injuries. The two passengers sustained non-life threatening injuries. The cause is attributed to vehicle excessive speed for the road conditions.

***This accident could have been prevented, just ask the two survivors.***




Unless otherwise posted the on post speed limit is 15 mph or 25 kph.

### **IMPORTANT INFORMATION TO REMEMBER:**

- Obey and comply with the posted speed limit and traffic signs.
- **Be attentive and drive responsibility.**
- Always wear your seat belt.
- **Keep your eyes moving. Be alert for changes in the road conditions.**
- When a passenger, remain alert, help the driver, when they violate policy, let them know.
- **Complete regular vehicle PMCS and never operate a unsafe vehicle.**

Slow down,  
leave racing  
to the  
professionals!!



**“SAFETY IS INTEGRAL TO THE WARRIOR”**  
USFOR-A Safety Office: DSN 318-449-4832